

Integrated Silicon Solution, Inc. (ISSI)

1940 Zanker Road, San Jose, CA 95112, USA

Corporate Registration Includes:

Integrated Silicon Solution, Inc. (Shanghai)

No. 12-13, Lane 647, Songtao Road, Zhangjiang Hi-Tech Park
Pudong New Area, Shanghai, 201203, China

Integrated Silicon Solution, Inc.

No. 2, Technology Road, V, Hsinchu Science Park, Hsinchu, Taiwan

with an off-site facility located at:

Integrated Silicon Soluton, Inc.

7F, No. 106, Sec. 1, Hsin-Tai 5th Road, Hsi-Chih, Taipei County, Taiwan

Underwriters Laboratories Inc.® (UL) issues this certificate to the Firm named above, after assessing the Firm's quality system and finding it in compliance with

ISO 9001:2000

EN ISO 9001:2000; BS EN ISO 9001:2000; ANSI/ASQ Q9001:2000

for the following scope of registration

3674 (US): Semiconductors and Related Devices

The design of integrated circuits. The management of outsourced integrated circuit production activities. The remote location at 7F, No. 106, Sec. 1, Hsin-Tai 5th Road, Hsi-Chih, Taipei County, Taiwan performs the following primary functions: sales and marketing activities.

Further clarifications regarding the scope of this certificate and the applicability of ISO 9001:2000 requirements may be obtained by consulting the organization.

This quality system registration is included in UL's Directory of Registered Firms and applies to the provision of goods and/or services as specified in the scope of registration from the address(es) shown above. By issuance of this certificate the firm represents that it will maintain its registration in accordance with the applicable requirements. This certificate is not transferable and remains the property of Underwriters Laboratories Inc. ®.

File Number: A12962 Volume: 1
Original Certification Date: March 29, 2004
ISO 9001:2000 Issue Date: March 29, 2004
Revision Date: November 3, 2008
Recertification Date: November 29, 2008
Renewal Date: November 28, 2011



John H. Schmidt
Senior Vice President, Chief Development Officer

